ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0058, W0081, W0025, W0036, W0033, W0047, W0044	NA, 14th Crs	Kodigehalli village
Segment No.	**Total Length (m)**	
8/C-W0058/S110859	114.52	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	25.60	77.575739	13.059780	77.575857	13.059635	W0044	DEAD END
2	58.09	77.574819	13.060267	77.575342	13.060152	W0027	W0033
3	30.83	77.576859	13.061762	77.577131	13.061679	W0081	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	008-16-000004
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/209/2015-16	12/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/02/2016	11/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.N.SHASHIDHAR		0.00
Phone No.	**E-Mail ID**	

45182353

Field Inspection Details

Number of Trees	Any Other Information	Name
5		Sirnivas murthy
Date of Inspection	**Remarks**	
20/06/2016	completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	20/06/2016	20/07/2016	COMPLETED
SE	VASU K M	20/06/2016	20/07/2016	COMPLETED
EE	YARAPPA REDDY	20/06/2016	20/07/2016	COMPLETED
AEE	Rajanikanth	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0058, W0081, W0025, W0036,

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0208	NA	Kodigehalli village Surrounding
Segment No.	**Total Length (m)**	
8/S-W0208/S112648	60.42	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	60.42	77.576783	13.059160	77.577340	13.059152	W0303	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	008-16-000004
Work Order No.	**Work Order Date**	**Period of Extention**
BTP/BBMP/E-PMT/209/2015-16	12/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/02/2016	11/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.N.SHASHIDHAR		0.00
Phone No.	**E-Mail ID**	
9845182353		

Field Inspection Details

Number of Trees	Any Other Information	Name
3		Sirnivas murthy
Date of Inspection	**Remarks**	
20/06/2016	completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	20/06/2016	20/07/2016	COMPLETED
SE	VASU K M	20/06/2016	20/07/2016	COMPLETED
EE	YARAPPA REDDY	20/06/2016	20/07/2016	COMPLETED
AEE	Rajanikanth	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0064	NA	Kodigehalli village Surrounding
Segment No.	**Total Length (m)**	
8/S-W0064/S104201	77.48	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	77.48	77.576657	13.061523	77.577349	13.061348	W0081	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	008-16-000004
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/209/2015-16	12/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
15/02/2016	11/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.N.SHASHIDHAR		0.00
Phone No.	**E-Mail ID**	
9845182353		

Field Inspection Details

Number of Trees	Any Other Information	Name
2		srinivasa murthy
Date of Inspection	**Remarks**	
20/06/2016		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	20/06/2016	20/07/2016	COMPLETED
SE	VASU K M	20/06/2016	20/07/2016	COMPLETED
EE	YARAPPA REDDY	20/06/2016	20/07/2016	COMPLETED
AEE	Rajanikanth	20/06/2016	20/07/2016	COMPLETED
AE	Srinivas Murthy	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	8	Kodigehalli
Street ID	**Street Name**	**Significant Landmark**
W0323	10th Crs Lakshmi Sagar Lyt	Kodigehalli village Surrounding
Segment No.	**Total Length (m)**	
8/S-W0323/S111607	89.48	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	89.48	77.578308	13.059484	77.578102	13.058700	RI-A23	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	4900000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvements to Roads and Drain at Kodigehalli village Surrounding inward no 8 Kodigehalli Sub-Division Yelahanka zone	008-16-000004
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/209/2015-16	12/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
12/02/2016	11/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.N.SHASHIDHAR		0.00
Phone No.	**E-Mail ID**	
9845182353		

Field Inspection Details

Number of Trees	Any Other Information	Name
2		Sirnivas murthy
Date of Inspection	**Remarks**	
20/06/2016	completed	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	20/06/2016	20/07/2016	COMPLETED

	VASU K M	20/06/2016	20/07/2016	COMPLETED
EE	YARAPPA REDDY	20/06/2016	20/07/2016	COMPLETED
AEE	Rajanikanth	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED
AE	SRINIVASA MURTHY	20/06/2016	20/07/2016	COMPLETED